





September 28, 2012

State of Tennessee Department of Education 6th Floor, Andrew Johnson Tower 710 James Robertson Parkway Nashville, TN 37243-0375

RE: 2011 Public Chapter 465 Underutilized and Vacant School Facilities

Please find enclosed a catalog of underutilized and vacant school facilities in accordance with 2011 Public Chapter 465 on behalf of the Shelby County Schools District.

The catalog includes the former Eads Elementary School located at 12010 Highway 64, Arlington, Tennessee 38002. Currently, the structure is vacant and has been identified as hazardous and in need of demolition following an inspection by the Shelby County Schools Facilities and Maintenance Department.

For more information regarding this submittal, please contact the Planning Department at (901) 321-2235 or Margaret Gilmore, Curriculum and Instruction Specialist at (901) 321-2572.

Regards.

Nedra L. Jones, AIC Planning Specialist

Enclosure

Cc: John Aitken, Superintendent

Tim Setterlund, Asst. Superintendent Phillip M. Simpson, Chief of Operations

Margaret Gilmore, Specialist

Justin P. Wilson, Comptroller Rich Haglund, Director of Charter Schools

Eads Elementary School

Address: 12010 Highway 64, Arlington, TN 38002

Year Constructed: 1953

Renovations/Additions: N/A

None

Portables:

13,400

Total SF:

Site Acreage:

1.83



Facility Component Rating Scale		SCHOOL NAME: EADS ELEMENTARY	DATE: September 2012
		To the second se	
Excellent	can be maintained in a "like new" condition and	can be maintained in a "like new" condition and continually meet all building code and functional requirements with only minimal routine maintenance	with only minimal routine maintenance
	does not meet the definition of "excellent," but	does not meet the definition of "excellent," but the structural integrity is sound and the component can meet building code and functional requirements with only	uilding code and functional requirements with only
Good	routine or preventive maintenance or minor repairs that do not hinder its use	pairs that do not hinder its use	
	structural integrity is sound, but the maintenant	e that it meets build	ling code or functional requirements hinder, but do not disrupt the
Fair	component's use		
	יבור בין מייר בין נייר שני מרומי מיי ווירפן ווי	see the second s	uliellierits are costly and disrupt the facilities use

			Insen	check mark	Insert check mark to rate each component as Excellent, Good, Fair, Poor, Repair or Replace	e		
Site	Excellent	Good	Fair	Poor		Repair	Replace	Estimated Cost
Parking Lots				×			- Compression	- Continuent and a
Driveways				×				•
Sidewalks				×				
Playground				×				
Site Drainage				×				
Dumpster Area				×				
Directional Signage				×				
Lighting				×				
Subtotal								S
Exterior Building	Excellent	Good	Fair	Poor	Explain Deficiencies:	Repair	Replace	Estimated Cost
Paintable Surfaces				×				
Doors				×				
Brick and Mortar				×				
Lighting				×				
Cabling				×				
Subtotal								
Interior Finishes	Excellent	Good	Fair	Poor	Explain Deficiencies:	Repair	Replace	estimated Cost
Walls				×				
Ceiling Tiles				×				
Sinks				×				
Counters				×				
Flooring				×				

1

Eads ES.xlsx

			Inser	t check mark	Insert check mark to rate each component as Excellent, Good, Fair, Poor, Repair or Replace	R		
Site	Excellent	Good	Fair	Poor		Repair	Replace	Estimated Cost
Lighting				×		pu	inpiden	rammarca coat
Subtotal								·
ADA Accessibility	Excellent	Good	Fair	Poor	Explain Deficiences:	Repair	Replace	Estimated Cost
Parking				×			- Indian	-Jenning Co.
Building Access				×				
Playground				×				
Subtotal								0
Food Services	Excellent	Good	Fair	Poor	Explain Deficiences:	Repair	Renlace	Estimated Cost
Lighting				*				
Service Areas				×				
Storage Areas				×				
Serving Lines				×				
Refrigerant lines				×				
Equipment				×				
Shelving				×				
Sinks				×				
Subtotal								0
Structural	Excellent	Good	Fair	Poor	Explain Delalences:	Repair	Replace	Estimated Cost
Foundation				×				
Cracks				×				
Separations				×				
Mechanical				×				
HVAC				×				
Chillers				×				
Sprinker System				×				
Subtotal								0
Electrical	Excellent	Good	Fair	Poor	Explain Deficiences:	Repair	Replace	Estimated Cost
HVAC				×				
Clocks				×				
Intercoms				×				
Fire Alarms				×				
Security Systems				×				
				,				

Eads ES.xlsx

			Inser	t check mark	Insert check mark to rate each component as Excellent, Good, Fair, Poor, Repair or Replace			
Site	Excellent	Good	Fair	Poor	Explain Deficiencies:	Repair	Replace	Estimated Cost
Technology/Networking				×				
Lighting				×				
Electrial Outlets				×		2		
Subtotal								0
List identification number and manufacturer of each portable on campus	nd manufactu	irer of eac	h portabl	e on campus				
Portables	Excellent	Good	Fair	Poor	Explain Deficiences:	Repair	Replace	Estimated Cost
Ceiling Tiles					No portables on site		•	
HVAC								
Flooring								
Foundation								
Access Ramps								
Technology/Networking								
Subtotal								. S
Notes:								
					Suspect underground storage tank and lead paint issues			
					Significant asbestos issues			
					Building is a safety hazard, cannot be repaired and needs to be			
			8		demolished			
					Cost estimates cannot be reliably developed			
Overall Facility Rating				×				
Total Estimated Cost		Estimo	ited demo	Estimated demolition cost				\$ 150,000.00